COMMONWEALTH OF KENTUCKY

BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY POWER COMPANY D/B/A AMERICAN ELECTRIC POWER)
ALLEGED FAILURE TO COMPLY WITH) CASE NO. 98-59 ⁻¹
COMMISSION ADMINISTRATIVE)
REGULATION 807 KAR 5:006,)
SECTION 26(1)(a))

ORDER

Kentucky Power Company, d/b/a American Electric Power ("Kentucky Power"), is a Kentucky corporation engaged in the generation, transmission, and distribution of electricity to the public for compensation for lights, heat, power, and other uses and is a utility subject to Commission jurisdiction. KRS 278.010(3)(a).

KRS 278.280(2) directs that the Commission prescribe rules and regulations for the performance of services by utilities. Pursuant to statutory directive, the Commission promulgated Administrative Regulation 807 KAR 5:006, Section 26(1)(a), which requires that a utility shall notify the Commission by telephone or electronic mail within two (2) hours following the discovery of any utility-related accident requiring in-patient over night hospitalization of an employee.

Commission Staff has submitted to the Commission a Utility Accident Report dated August 21, 1998, attached hereto, which alleges that:

1. On July 8, 1998 at approximately 7:00 p.m., Kentucky Power employee, Albert J. Grillon, climbed Kentucky Power electric pole No. 272-858 near Walker Branch Road in Perry County, Kentucky, to replace a lightning arrestor on a CSP transformer.

The pole gave way and severed at and below ground level as Grillon fell from the pole.

The customer was a sole witness.

- 2. Kentucky Power was notified of the accident on the same evening at 7:05 p.m. Later that night, Grillon again was evacuated by air from the local hospital in Perry County to St. Joseph's Hospital, Lexington, Kentucky, where he was hospitalized over night.
- 3. Kentucky Power began its official investigation of the accident at 7:00 a.m. the next day, July 9,1998. The Commission was notified of the accident on July 9, 1998 at 8:22 a.m. and the Commission received a written accident report from Kentucky Power on July 13, 1998.

The Commission, based upon the facts contained in the Utility Accident Investigation Report, finds sufficient evidence to believe that Kentucky Power has failed to comply with 807 KAR 5:006, Section 26(1)(a).

The Commission, on its own motion, HEREBY ORDERS that:

- 1. Kentucky Power shall submit to the Commission within 20 days of the date of this Order a written response to the allegations contained in the Utility Accident Investigation Report.
- 2. Kentucky Power shall appear on the 12th day of January, 1999 at 10:00 a.m., Eastern Standard Time, in Hearing Room 1 of the Commission's offices at 730 Schenkel Lane, Frankfort, Kentucky for the purposes of presenting evidence regarding the alleged violation of Commission Regulation 807 KAR 5:006, Section 26(1)(a), and of showing cause, if any, why it should not be subject to the penalties prescribed in KRS 278.990(1) for the alleged violation.

- 3. The Utility Accident Investigation Report dated August 21, 1998 is hereby made a part of the record herein.
- 4. Any request for an informal conference with Commission Staff to consider any matter which would expedite the handling or disposition of this proceeding shall be filed with the Commission no later than 20 days from the date of this Order.

Done at Frankfort, Kentucky, this 20th day of November, 1998.

PUBLIC SERVICE COMMISSION

Chairman

Vice Chairman

Commissioner

ATTEST

Executive Director

APPENDIX

AN APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE COMMISSION IN CASE NO. 98-591 DATED NOVEMBER 20, 1998

UTILITY ACCIDENT INVESTIGATION REPORT American Electric Power - Hazard **Utility:** Joe Pemberton Reported By: Dates & Times Accident Occurred: 07/08/98 - 7:00 p.m. Utility Notified: 07/08/98 - 7:05 p.m. **PSC Notified:** 07/09/98 - 8:22 a.m. Investigated: 07/13/98 Written Report Rcvd: 07/13/98 Location of Accident: Walkers Branch Road, Allais, Hazard, Kentucky Mr. Albert J. Grillon was injured when the transformer pole installation he had Description of climbed fell with him. Mr. Grillon visually checked and mechanically sounded Accident: the pole with his pliers to determine that the pole was safe to climb. Victims: Fatal: 45 Albert J. Grillon No Age: Name: 1400 East Main Street, Hazard, Kentucky/American Electric Power Addr./Empl.: Broken vertebra in neck and back Injuries: Witnesses: Name Address/Employment Walker Branch Road, Consumer Raymond Banks Address/Employment Name American Electric Power employee Mike Lasslo American Electric Power employee George Tackett Sources of **PSC Engineering Staff** Information: John Land, on site Investigator KAR 5:006, Section 26 (1)(a). The utility did not report the accident with 2 Probable Violations:

hours. See attached letter, dated August 21, 1998

August 21, 1998

Line Clearances At Point of Accident:	Measured	Minimum Allowed by NESC	Applicable NESC Edition ¹ 1990	Volt.	Constr. Date
			N/A		
Date of Measurement:	N/A				
Approximate Temp.:	N/A				
Measurements Made By:	N/A				
Investigated By:	John W. Land				
Signed:	Kolmu)	Land			
		•			

- Attachments A. American Electric Power's Accident Report
 - B. Photographs of Accident Site

Current edition adopted by the Commission. If clearances are not in compliance with the current edition, then the edition in effect when the facilities were last constructed or modified would apply.

Δ	tta	ch	m	ρn	+	Δ
Δ	ııa	CII	ш	CII	L	A

American Electric Power's Accident Report



Date.

August 21, 1998

Subject

PSC Notification of Albert Grillon Accident of July 8, 1998

From:

Michael G. Lasslo/AEP/Hazard Service Center

To:

John Land/Kentucky PSC

Albert's accident occurred at approximately 7:00PM on the evening of July 8, 1998. He was transported to the ARH Medical Center by ambulance for emergency care and evaluation. By 12 Midnight of that same evening the ARH staff determined that Albert should be evacuated to St. Joseph Hospital in Lexington, Ky. for further care and evaluation of his injuries. His immediate supervisor, George Tackett, accompanied Albert and his immediate family to Lexington.

Our official investigation of the accident did not start until 7:00AM the morning of July 9, 1998. At that time George was contacted for an update of Albert's condition and he reported that Albert had been kept overnight and that Albert would require additional medical treatment for his injuries including surgery.

At that time, it was determined that the accident met the reporting requirements of the Kentucky PSC. The PSC was notified at 8:22AM on the same morning of July 9, 1998.

If you have any questions or need more information regarding this matter, please contact me at 606-436-1340.

Sincerely.

Michael G. Lasslo

Customer Service Superintendent

Hazard Service Center



Martha M. Morton, Manager, Electric Branch
Public Service Commission
P. O. Box 615
Frankfort, Kentucky 40602

July 13, 1998

Dear Ms. Morton:

Attached is a copy of the Accident Investigation Report for the accident which occurred on July 8, 1998 involving our employee, Albert J. Grillon.

This report was prepared and signed by our local Accident Investigating Committee; and the original is now in the office of our Region Manager, Dave Lang, awaiting his signature.

Sincerely,

John R. Fliehman

Reliability Superintendent

JRF:cr

Attachment

Form PS-92 (Rev. 7/91) 7095(R1-68)AE




ACCIDENT INVESTIGATION REPORT PART I


Name Albert J. Grillon	Age 45 Sex M S.S.# 143-48-6581
Classification Line Mechanic "A"	
ClassificationLine Mechanic "A"	
How Long in Classification 8 years	
17 2000	Date of Employment: 12-24-80
How Long in Department 17 years	Date of Employment 12-24-80
	PARTII
Accident Classification at	nd Type (Check All Applicable Lines)
Fatality	_ Electrical Contact First Aid
	Mana Affan
x Lost Workday	Electrical Flash Near Miss
Restricted Activity	Medical Case Vehicle Accident
The second secon	the state of the s
Weather Conditions Calm	
Date of Accident 7-8-98 Time 7-00 P	• <u>-</u>
the second of th	The control of the co
Reported To Whom 911	Date Time7:05 P.M.
Where did Accident Occur? (Be specific, i.e., overhead	d line, power plants, etc.; if inside plant, give location)
	and and a supplied to the supp
walkers Branch Road, Allais	
Unit/Department Energy-Delivery	Town Hazard State KY
Names of Witnesses to Accident Raymond Ba	inks (Customer)
Walkers Branch Road	and the second of the second contract of the second of
the state of the s	
Name and Classification of Supervisor in Charge of Wo	ork Albert Grillon, Line Mechanic "A"
,	
(Employee working alone)	
Job Briefing Conducted By: Person in C	harge of Work
X Self-Briefing	

DESCRIPTION OF ACCIDENT (If Insufficient Space - Continue on the back or an extra sheet) (If Applicable, Attach sketch)

Unit/Department	Energy Delivery	Date 7-8-98	Time _ 7:00 P.M.
Place of Accident_	Walkers Branch Road	Allais	
Classification of Inj	ured Line Mechanic '	'A" Period of	Disability 6 mos. to 1 y
Extent of Injuries	Broken vertebra in	neck and back	·· · · · · · · · · · · · · · · · · · ·
lightning a phase line	dent Line Mechanic "A" rrestor on a CSP tran to trip out. Before	sformer that had cau climbing the pole. L	sed a main single
sounded the	·40' class 6 pole wit	h a pair of pliers. that it would be saf	He found that it
climbing the	e pole, it started to scend the pole and ma his gaffs became lod	give away with him. de about three steps	Line Mechanic "A" down the pole
dislodging t	the gaff, he fell off the ground. He land	the pole, approximat	tely 20 feet, as the
(Sketch Atta	ached)		
above receiv	ttee was unable to in yed from George Tacker vice Superintendent, to the injured employe	t Team Leader, and who were at the SCer	Michael G. Lasslo
			3 7
Does the Investigating	ng Committee feel it has a clear picto	ure of just what caused the acciden	nt? X YesNo
Please ExplainT judgment cal	he experienced Line M l after sounding the	echanic "A" of eight	years made a
safe to clim	 Even though he co 	uld have performed a	more thorough
may have sti	f the pole, such as u 11 determined that th ted off below ground	e pole was safe, not	knowing that the

What action is recommended to prevent recurrence of this accident? Perform more thorough checks of poles at groundline, including digging around pole to check just below
groundline with hammer and screwdriver Have a refresher course in
Safety Meetings on procedures of testing poles before climbing. Refer
to Reference Material, Power Pro D-146.
We can also refer to Safety Manual Section 6.06, "When there is any
doubt, a person may want to consider tying off the pole, or delaying the
climb until further help arrives"
NOTE: This particular pole was installed in 1948. The Kentucky Public
Service Commission requires a visible inspection of circuits biannually.
The last visible inspection of this circuit was performed in November 199
Part IV
/ // Investigating Committee /
Signed: Hrug SARAM Q I ENGINEER TECHNOLOGIST III FREARCH
Signed: \[1 \lambda \la
// (Symmonson)
Alymon R. France 1 Line Mech "A" 1 Hazard.
1: 20 1) 1/2 EA/2 2.1
1 June 17 June
N. M. 10 1998
Date: - 4 44 10, 1978-
, ,
Part V
I have reviewed the Accident Investigation Report.
Signed:
•
Title:
Date of Review:





LOCATION WALKERBRANCH ROAD AT ALLAIS

SCALE : NONE

Form 5757 (Rev. 7/91)

CHECKLIST OF ACCIDENT FACTORS

Check the	one unsa	are conditions and/or act which best describes the cause of the accident.
TYPE OF	UNSAFE	CONDITION (CONTROLLABLE BY COMPANY OR EMPLOYEE)
	101.	Equipment Improperly Guarded
	102.	
	103.	
	104.	
	105.	
	106.	
	107.	
 	108.	
	109.	
	,,,,	
TYPE OF U	INSAFE.	ACT:
		is coded, the reason for the unsafe act must be coded also.
	201.	Operating without authority, failure to secure or warn
	202.	Moving, operating or working at unsafe speed
	203.	Making safety devices inoperative .
	204.	Using unsafe equipment, hands instead of equipment or equipment unsafety
	205.	Unsafe loading, placing, mixing, combining, etc.
	206.	Taking unsafe position or posture
	207.	Working on moving or dangerous equipment
	208.	Distracting, teasing, abusing, startling, horseplay, etc.
·	209.	Taking a short cut
	210.	
	211.	Other (please explain)
	2	
REASON F	OR UNS	AFE ACT"
	301.	Failure to Analyze
	302.	Disregard of Instruction
	3 03.	Attitude
	304.	Physical Condition
	305.	Lack of Knowledge, Skill or Experience
	306 :	Other (please explain)
•		
±		
		IOLATIONS:
NONE		cident (List paragraph numbers)
FUNDAMEN	ITALS O	F SAFE WORK PROCEDURES VIOLATIONS
	1.	No electrical equipment is dead unless de-energized and grounded.
	2.	Never go within reaching or falling distance of energized equipment unless properly protected.
	3.	Don't take shortcuts - safety and work procedures cannot be separated.
FUNDAMEN	ITALS O	
. 0110711161	1.	When driving, concentrate only on one thing - defensive driving.
	i. 2	Right-of-way is given, never taken.
	3.	Be certain it is "clear to the rea" before backing.
	J.	DE LEIGHIN N D. LICON IV HIE IEG DENVI VOLVANI.

	RECEIVED BY / CAMPBOL	4 Griccon	GS-SL-	DS-GF - 3.	R. HAZARd	OP. 3311
	DATE 7-8-98 REASON CALL	000	ower		SCHTHEY S NOVER	
	NAME CUSTOMERS DARRELL	KEYES		CUSTO PHONE		391
	ADDRESS WALKEN	s BK			- D=0	=== C()
7.5	: HAZARI	1/9	NU	MBER 273	2-858 _	AT ISOLATING DEVICE
2 E E	STATION BLUEGRA	CIACUIT	14/ 1/	IUN	NO. OF PHASES	
FOR	ISOLATING DEVICE 1-LC	0		SIZE FUSE BLOW! SIZE RECLOSER /	W LS D	FAULTED FAULTED
	CAUSE BAY CSP L	TWIARR - F	ole fc	SIZE SECT.	17h Emp	loyes-
	DAMAGED NATERIAL XFM C-	- Pule	MANUFACTURER		EQUICATURAM RASY	3
	SERIAL OR CATALOG TO			·	TYPE	5125
N L		YPE.CONSTRUCTION, SPAN LENGT	H.CONDUCTOR SPACE	NG. ETC		
 P.O.	VOLTAGE INVOLVED 7. 2	KV		WEATH	IER SEVERITY	/
MAGN	UNDERGROUND CABLE			GORIES	1040 (KVA	CONDITION OPTIONAL?
40 t		P.M. TIME ON	NO. OF (1) 5	50	TIME ON 2:01 0	0. 0f UST (2) 10
JBLE		E BRUKO	PTY	BASE	1217A-	AnoTheic
ROUI	ROTTEN POLO	<u> 4711.</u>	 			
)	SY WONTHLY		CUSTO			
	REPORT NO. WO.	DA. 7 8 YR. 9	sr	۸. <u>ا ً ا ا</u>	15 CIR [16 17 DIV.	18 19 OPER. 20 21
	POLE NO. 22 25 28	31 POLE NO. 32	35	"111"	TIME 45 48 TI	ME 49 52 DAYS 55
	NO. OF 59 TIME 64	67 DAYS 70 MO. 05,71	74 D/C 1		122 24; YR. 125	26,COND.;27 29;
	cust. law (2)	(2) Cust	l I Iconel	CODE 1 MFC	id	19176
	CUST. JOH (2) 1-PH 30 31 OWND/UG 32 OWND P CONF. 35 STR/UG (OLE 33 FUSE/39 CABLE REC/	1 FUSE 0-H 7-SILVE TYPE 1-T 4-SILVE 2 K 5-CUR.	E ST 9- DIST. ,42		SIZE AT TYPE AT DMG
	1-PH 130 31 OVHO/UG 132 OVHO P	OLE 33 FUSE/39 CABLE REC!	TYPE 1-7 4-5H.VE 2 K S-CUR.	P ST 9-DIST. 42 P K POWER LIM. 9-OTHER	1500 ,43, ,44 45	COND 46 TYPE 47

•

V

→→→ HAZARD-DISP 07/09/98 THU 02:11 FAX 07/08/98 23:55 FAX 6064361275 **2**1001 EPRM MCSAD7 03 03011 02/25/76 034-420-061-0 ACTIVE Y BANKS FRED 020 022 RSW-RS 6 01 HAZARD 1035 WALKER BR RD TRLR RVCL CD 020 RES WITH SPACE HTG ENGR. NO TAR CD 022 RESIDENTIAL - WATER HEATER LAST PARM CRG 02/26/76 SIC CD 000000 RESID, VACANT BLDGS EFF PARK DATE 02/26/76 ETP PARM DATE ***TAX INPUTS*** ***INDICATORS*** ***INFUT FIELDS*** EXHP = FORM NO TYPE CL PHASE EMP/ASSOC CO PHASE 2 RES SERV MUL NO % CHAR CD TOD DISC FL * BLEC DM PROV DEM CK PNT COMM CD 302 TAX DIST 214900 ESTIMATE FL UNMIR SERV MULT PRORATE FL Y CONTRA CO CD == = VALIDATIONS *** EQP ADJ FL N OFP KW PL IRR USE 330272000858 TRNFRM PL NO CURTAILABLE BILLING DEMAND 330272000858 SERV PL NO NOM DELV VLTG NOM DELV VLTG 2 SEND BILL Y RMK +9081 NOT AUTHORIZED TO UPDATE - INQUIRY ASSUMED NEET DATA 11 BIL PRM2 12-CANCEL MY. S. V. 123- SIMON LUNCE GREG FUGATE 47 67 4 **2**00 4.5 1 St 72 DOVE STRONG N CREW 2:01 JAMIE ROSE WITH THE PIE & VIRGIL HURT $\Sigma':$ - • • . : : : :

KENTUCKY' POWER COMPANY

ACCIDENT RECORD

12-2	4-80		Ì	Emp. _ Date					Na me	Albert Joseph Grillon
Date	Minor	Med.	Non Occ. Inj.	Dis. Inj.	Days Lost	Auto	Class	Est Cos	Superviso	T Description and/or Remarks
<u> </u>	X				0				Jim Mullins	Employee was spotting a pole on a hill side when he walked into some
										briars causing a thorn to be lodge in his right bicep.
30-82	х				0			-	Willis Strong	Employee was cutting a small brance out of the way with a knife when the knife slipped and
-18-83	х				0				Willis Strong	knife slipped and cut his left indefinger Employee was climbing a pole when
										and he snagged it on a nail in the pole, causine a laceration in the
										paim of the right hand.
2-12-83	_х				_0				Bruce Lindon	Employee was trying to free the loo end of a winch line when it broke a
-3-84	х				0				George Tackett	pierced his leather glove and punct d the middle finger on the left han Employee was rolling up the hose to
								·	Tackett	steam cleaner when he lacerated his right index finger on the broken steel pressure core.
2-15-89	X				0				Simon Lunce	Employee had parked bucket truck ar
										was exiting vehicle, stepped onto step (which is fuel tank; foot slipped and he lost his balance and
										fell, landing on concrete, bruising buttocks. (Fuel had spilled onto
										step and it was wet; also, employee had on overshoes which were wet and slippery.)
-17-89	X				0	·			A. R. Brashear	Employee was cutting a tree from se
		_								vice when it kicked back and fell, hitting him on the front of his rig. shoulder and check, bruising his
-2-90		X			2			11	George R.	right shoulder.
									Engle	Employee was loading 40-foot poles onto a pole trailer. Shile sliding sling on pole, he ran a splinter in
										his right index finger, through a leather glove.
-15-92			- :	x apr	rox.				obert E. addell	Employee was climbing CCA pole #160-
				_						to install DD light; stopped ascend: to belt off around pole above teleph cable; gait cut out of pole. He fel
	#_									approx. 8 feet when right gaff caugh

KENTUCKY POWER COMPANY

ACCIDENT RECORD

Emp 12-24-80 Date

Name Albert Grillon

_			-		-						Albert Grillon
=	Date	Minor	Med.	Non Occ Inj.	Dis Inj	Days Lost		Class	Est.	Supervisor	Description and/or Rer
1	-7-93						х		549.		e Backed into a
								to	repa	r Trans AM.	1986 Pontiac Trans AM on Ball Creek
											of Talcum, Ky.
12	2 - 3 - 9 3						х	#1 1	,000	Allen Walke	Vehicle #1 was r parked off the
			<u> </u>					(Both	comp	any vehicles	road. Employee) went to turn the
			<u> </u>					_			material bucket truck and when
											backing up struck vehicle #1.
5 <u>-9</u>	9-94	х								Mike Lasslo	Employee was dismounting off of
											back of truck and pin was missing
****											from step so step gave way when he pu
											his weight on it
							$\neg \uparrow$				causing him to fall into ditch striking
				╂──-							back of his neck.
											(Sore and bruised neck.)
_						-				Cara	
<u>3. :</u>	30·96	- χ				D				George I	see sting to cheek
						-					
											
											······································
						_					
						-					

STATUS	GRADE EXAM																		T					-									+		-	!			-T
PROMOTABILITY STATUS	DATE		/nr	2 2 2	-//iii	./hr	5 n/hr	n/hr	p/hr.	ᠰ	n/hr.		$\bar{}$	/hr.	p/hr.	p/hr.	p/hr.	1 /hz		-p/nr	n/hr	77.11	n/hr	/hx	0/hr.	n/hr	p/hr	p/hr.	n/hr	p/lir.	p/hr.	p/hr.	1,5			-			
		RAIE	0.62	7 7 7	0.9	6.9	7,40	7 405	7.665	7,924	8.63	4	<u> </u>	9.74	10.03	10.53	10.850	1	J	-	12 33	+-	185	2 2	.39	73	15,325	15.919	16.67	$\overline{}$		18,670	79.97					+	1
	10 345	1	2	,	S	TR.	۲,		TP	ТР	C	dI.	G,	ပ	TP	ဗ	TP	σĘ			9	ر (U	ن	U	Ъ	TP	Ê	S	TP	9	ن	Ċ						
	-	Z C	40	╁	10	<u> </u>	_		8	-		æ	æ		<u>۳</u>	8	Я	R	ď	-	2	2	ĸ	2	×	R	2	~	~	≃ 	~	~		_	1		_ _	<u> </u>	_
		DISTRICT	Haz	Ha7	Haz.	Haz.	Haz.	Haz.	Haz	Haz.	Haz.	Haz.	Haz.	Haz	Haz	Haz.	Haz.	Haz.	Haz		Haz.	Haz	Haz.	Haz.	Haz.	Haz.	Haz.	Haz.	Haz	Llaz	Haz.	Ilaz.							
ORY		Cievania.	T&D	(181)	T&D	T&D	ጥይD	T&D	T&D	T&D	T&D	T $^{\omega}$ D	T&D	T&D	T&D	1	J T&D	T&D	T&D		T&D	T&D	T&D	T&D	T&D	ፐጹቦ	T&D	140	TgD	TED	191)	T&D							
MPLOYMENT HISTO			5850-335132	5850-346439		999-5\$620-346439	5630-346439	5630-346139	5630-346439	620-246439	999-55630-346439	5630-346439	5780-	5780-346439	12/80-246439	55780-346439	55780-3464	-55780-346439	55780-346439	-67922-346439			-67922-346439	999-67922-346439	-67922-346439	999-67918-346439	67918-346439	6/918-346439	999-0/918-546439	999-67918-346439	0.10-040409	918-346439							
E M P L	10 1411	. C	20-5	520-5	520-59	9-5		999-5	999-5	19-55	9-53			989-3	1 1		-666	666	999	66	66	666	666	666	999	999+		566	565	999-(0=0							_
llon, Albert Jo		Station Mac	Mechanic "D"	"D"	on Mechanic "D"	Mechanic "D"	Line Mechanic "C"	Line Mechanic "C"	Mechanic "C"	Mechanic "C"	Mechanic "C"	Mechanic "C"	Mechanic "B"	Mechanic "B"	Mechanic "B"	Line Mechanic "B"	Line Mechanic "B"	- 1	Line Mechanic B		Line Mechanic B	Mechanic		Mechanic	Mechanic	Line Mechanic A	Line Mechanic A	Line Mechanic A	Line Mechanic A	1	V								
Gri	I I I I I I I I I I I I I I I I I I I				85	קנר	121	7.70	219	20	9	107	1,7) t	15.5	720	6,50	43	64		23	55		2	200	3 8	149	15	84	67	47	3/2	T					Ť	
	TAME EFFECTIVE	12-21-60	1-1-81	3-4-81	5-1-81	5-13-81	0-1/-0	18-57-0	7-1-81	VI 1	72-1-87	10-12-04	10-77-07	// 2 0/	Τ.	10 20 01	4-8-85		2-1-85	C8-T-6	5-1-86	5-1-87	2-1-88	2-1-89	6-7-90	7-9-00	12-18-90	S-1-91	6-14-91	5-1-92	5-1-93	h)-1-h	7-12-17			-			_

NAME OF THE PREVIOUS ENTOTIES AND ALDER THE PREVIOUS ENTOTIES AND ALOCATION AND ALLES THE PREVIOUS ENTOTIES AND ALOCATION AND ALLES THE PREVIOUS ENTOTIES AND ALOCATION AND ALLES THE PREVIOUS ENTOTES AND ALOCATION AND ALLES THE ALOCATION AND
--

KENINCKI, BOMEK COMBVIA

RECORD	ACCIDENT.	

in pole, causing injury to right kin	1	1	ì	1	il	1		11	ll.	1
approx. o reer when aren care bury to right kind	†	#	+	+		+		#		
cable; gait cut our of pole. He fel approx. 8 feet when right gaif caugh								1		1
to belt off around pole above teleph.		#	 	 -						
to install DD Light; stopped ascending	į				-		-{(1	·	
Employee was climbing CCA pole #160-	Maddell	1		+	+		╫			72-65
-0914 0100 100	Opert E.		1	1	ξ ! bbrox·	X e	-	N N	11	20-21-
leather glove.		1		1	1	+	 	╫		
his right index finger, through a		1	İ		-		-	#		
sling on pole, he ran a splinter in:						1	1	╫	┪	
onto a pole trailer. Shile slows			_L_	1	- (1		11	#	-	1
Employee was loading 40-foot poles		7		T	0			X	#	06-2-9
	GOIGE K.	Д			<u> </u>))	
ridht shoulder.					1		1		1	
syoniger and check, bruising his			J					_		
hitting him on the front of his rig.		1		1				Î		
Vice when it kicked back and fell,	1	#	 	- 						<u> </u>
Employee was cutting a tree from se-			1		0	1	ll	1	X	68-21-8
(.6.7044.77	A. R.	#	-} -	1		+	#	-∦	#	
had on overshoes which were wet and slippery.)			1.		1		-	1	1	
sed on orests also, employee	<u> </u>	#	 	+	<u>H</u>	+		-		
buttocks. (Fuel had spilled onto	}	l	1	1	1	1]]		1	
fell, landing on concrete, bruising		#	 	1	╬	 			11	
slipped and he lost his balance and	[l	1							
step (which is fuel tank; foot		#	1		1		╬	╫	╬	
was exiting vehicle, stepped onto			}		1	1	1	il .		
Employee had parked bucket truck an	əounq	1			0	†	╣		# ×	3-12-88
	u ou țs	1		İ	l	1	-		I	
steel pressure core.		1				1			1	
right index finger on the broken		#			<u> </u>			#	1	
steam cleaner when he lacerated his	Tackett	H		1	0	1			X	78-8-2
Employee was rolling up the left han	George	 	 -	ļ	<u> </u>	<u> </u>	1	1	1	
pierced his leather glove and punct		H	1	ļ	li		ll .			
end of a winch line when it broke a			 	-		 	-	<u> </u>		
Employee was trying to free the loo	Bruce			1	0		11	}	X	3-15-83
		 	 	 	<u> </u>		 	 		
palm of the right hand.		l	1	1			l l			•
pore, causine a laceration in the		 	 	-		 	 	 	}	
and he snagged it on a nail in the		∥ 、	-		ll .	}	I	l l		
his hook cut out, his hand slipped	Strong				0	 	#	 	Х	-18-83
Employee was climbing a pole when	SITTIM					1		A	^	58-81-
regari								 		
knife slipped and cut his left inde	· 	L			ļ	ĺ		l		
out of the way with a knife when the	Strong				0				Х	78-08-
Employee was cutting a small branc	silliw									
briars causing a thorn to be lodge in his right bicep.	į				1					
		ļ	ļ	<u> </u>					 	
Employee was spotting a pole on a hill side when he walked into some	aniliuM				0				X	18-22-6
- 20 ofor a prittons as aavoluma	mit									
Describtion and/or Remarks	Supervisor	3 so J	SSSIO	0308	Lost			· nau	Youin	Date
		.jsä	١	ľ	Days	.sid			:/	0.1.CU
		<u> </u>			'		noN	<u></u>	لحسط	
Albert Joseph Grillon	Изте					Date	ī		08-	12-24
						.qm3	1			
I .										

(ail Mike Larrie for accident invertigation (606) 436-1340

ACCIDENT AND TROUBLE REPORT FORM

TODAY'S DATE 7-9- 98	TIME 8122 AM
COMPANY AEP	•
PERSON REPORTING INCIDENT: NAME:	For Remberton
	Rehotely map.
ADDRESS: (cepland office
	606) 327-1274
ACCIDENT DESCRIPTION: Poll bake	and Albert Coilla 200
with the ende	Visit Company of the company of the
limbin ing expe	
22 4 (= 2/	
VICTIES NAMES: Differ + Gullar	
	SEX_ AGE_ DEATH_INJURY_
:	sex age deathinjury
LOCATION OF ACCIDENT: HAZA	P. P.D.
•	· · · · · · · · · · · · · · · · · · ·
TIME OF OCCURRENCE:	16 -1-5 22
TROUBLE DESCRIPTION:	
TIME OF OCCURRENCE:	
TIME OF RESUMPTION OF NORMAL SERV	ICE:
NUMBER OF CUSTOMERS AFFECTED:	
• • • •	SIGNED Esia Purell
	7-1 10

Attachment B

Photographs of Accident Site





